


250L/400L/500L 3-POINT SPREADER DIAGRAM



250L/400L/500L 3-POINT SPREADER PARTS LIST

REF NO.	PART NO.	DESCRIPTION	Q'TY
1	250001	Frame	1
2	250002	Bolt, Hex Head M10x20, Zinc	2
3	250003	Washer, Flat, 10mm, Zinc	5
4	250004	Hair Pin	4
5	250005	Rod, Flow Adjustment	1
6	250006	Lever, Adjustment	1
7	250007	Spring, Pressure	1
8	250008	Bolt, Hex Head M10x70, Zinc	1
9	250009	Handle, Rubber, 8x20	1
10	250010	Brace, Left	1
11	250011	Nut, Hex M10, Zinc	14
12	250012	Washer, Lock, 10mm, Zinc	10
13	250013	Rod, Selector, RX-LX	1
14	250014	Pin, Connection, $\varnothing 8 \times 16$	1
15	250015	Agitator	1
16	250016	Bolt, Hex Head M8x45, Zinc	1
17	250017	Lock Nut, M8	1
18	250018	Washer, Nylon, 25mm	1
19	250019	Bolt, Carriage, M10x25, Zinc	5
20	250020	Bar, Hopper Reinforcement	1
21	250021	Washer, Flat, 10.5mm, Zinc	1
22	250022	Hopper	1
23	250023	Retainer Bushing	1
24	250024	Hopper Support Pan	1
25	250025	Bolt, Carriage, M8x25, Zinc	6
26	250026	Washer, Flat, 8mm, Zinc	14
27	250027	Washer, Lock, 8mm, Zinc	14
28	250028	Nut, Hex M8, Zinc	15
29	250029	Seed Disc, Upper (2 holes)	1
30	250030	Distribution Disc, Lower (3 holes)	1
31	250031	Bolt, Hex Head M8x16, Zinc	8
32	250032	Vane, Fan	4
33	250033	Roll Pin, $\varnothing 8 \times 40$,	1
34	250034	Roll Pin, $\varnothing 6 \times 40$,	1
35	250035	Pin, Adjustment	1
36	250036	Spreading Disc (Spinner)	1
37	250037	Guard	1
38	250038	Block, Fixing	1
39	250039	Indicator	1
40	250040	Screw Wing, M6x16	1
41	250041	Bolt, Hex Head M10x30, Zinc	4
42	250042	Gearbox, 3 hole (complete)	1
43	250043	Bolt, Hex Head M10x110, Zinc	3
44	250044	PTO Assembly (complete)	1
45	250045	Washer, Flat, 32mm, Zinc	1
46	250046	Snap Ring, $\varnothing 38$	1
47	250047	Lock Nut, M10	1
48	250048	Washer, Special	4
49	250049	Washer, Nylon, 10mm	1
50	250050	Brace, Right	1

Optional

51	250051	Extended Retainer Bushing For Fitting Lock Nut	1
52	250052	Lock Nut M40x1.5	1
53	250053	Nylon Washer Flat 32mm	1